

SECRET

OUT57592

multi

P 212256Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2 AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 6317.

1966 JAN 21 23 14Z

24 JAN 1966

DISTRIBUTION	
Cy No.	Office
1	CS
2	CS
	ADMIN
	SEC E
	P&P
	CCD
	IFD
	FOO
	FOO/IO
345	TID
	IAO
	PAG
	DIAX-4
	SPAD
	NSA-LO
	DIA-AP

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-23 WAS USED IN MISSION 8068 FLOWN 20 JANUARY 1966.
 PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD.

B. 9R SIDE: EDGE FOG AND STATIC IS PRESENT ON BOTH SIDES
 THROUGHOUT THE MISSION. TITLE FLAKING OCCURRED ON FRAMES 584
 THROUGH 599. A BAND OF FOG PERPENDICULAR TO THE MAJOR AXIS IS PRE-
 SENT ON THE LAST FRAME OF THE MISSION. PRONOUNCED STREAKS OR
 STAINS ARE PRESENT ON THE BASE SIDE OF THE FILM ON FRAMES 1500
 THROUGH 1704. SIMILAR STREAKS OR STAINS ARE PRESENT ON NUMEROUS
 OTHER FRAMES BUT NOT AS PRONOUNCED. THE ANOMALY DOES NOT AFFECT
 THE IMAGERY AND IS POSSIBLY CAUSED BY INSUFFICIENT WASH DURING
 PROCESSING. A HEAT SPLICE IS BETWEEN FRAMES 279 AND 280. A
 MANUFACTURERS SPLICE IS PRESENT ON FRAME 1550 WITH ASSOCIATED EDGE
 FOG ON FRAMES 1548 AND 1553.

Advance copy
 Sanitized

Declassification Review by
 NSA/DoD

SECRET

-2-

C. 9L SIDE: NUMEROUS ROWS OF LONGITUDINAL MINUS DENSITY DOTS ARE PRESENT AT THE BEGINNING OF THE MISSION. THE DOTS ARE SPACED 1.65 INCHES APART AND GRADUALLY DISAPPEAR BY THE END OF THE MISSION. PRONOUNCED EDGE STATIC IS PRESENT ON THE FIRST FEW FRAMES ALONG THE OUTBOARD EDGE WHICH BECOME MINOR AND INTERMITTENT AS THE MISSION PROGRESSES. ROLLER CHATTER IS PRESENT THROUGHOUT ON THE INBOARD EDGE. EDGE FOG IS PRESENT ON BOTH EDGES THROUGHOUT. HEAT SPLICES ARE LOCATED BETWEEN FRAMES 908/909 AND 914/915. A MANUFACTURERS SPLICE IS PRESENT ON FRAME 1198.

D. THE FRAMES ARE TITLED 0000 THROUGH 1704.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS EXCEPT FOR THE POSSIBLE PROCESSING ANOMALY MENTIONED UNDER THE 9L SIDE.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS COVERED APPROXIMATELY 25 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-